

Parts Change Notice

CS-A24BD2P CS-A28BD2P CS-A34BD2P CS-A43BD2P CS-A50BD2P

Please revise the original parts list in the Service Manual to conform to the change(s) shown herein.
If new part numbers are shown, be sure to use them ordering parts.





Reason for Change

*The circled item indicates the reason. If no marking, see the Notes in the bottom column.

1. Improve performance	
2. Change of material or dimension	
3. To meet approved specification	
4. Standardization	
5. Addition	
6. Deletion	
7. Correction	
8. Other	

Interchangeability Code

**The circled item indicates the interchangeability. If no marking, see the Notes in the bottom column.

Parts	Set Production	
A Original New	 Early Late	Original or new parts may be used in early or late production set. Use original parts until exhausted, then stock new parts.
B Original New	 Early Late	Original parts may be used in early production sets only. New parts may be used in early or late production sets. Use original parts where possible, then stock new parts.
C Original New	 Early Late	New parts only may be used in early or late production sets. Stock new parts.
D Original New	 Early Late	Original parts may be used in early production sets only. New parts may be used in late production sets only. Stock both original and new parts.
E Other		

Part Number

Model No.	Ref. No.	Original Part No.	New Part No.	Notes	Part Name & Descriptions
CS-A24BD2P	8	P45-T07020	P45-T04490	7, C	FAN BASE AS.
CS-A28BD2P	8	P45-T07020	P45-T04490	7, C	FAN BASE AS.
CS-A34BD2P	8	P45-T06980	P45-T04270	7, C	FAN BASE AS.
CS-A43BD2P	8	P45-T06980	P45-T04270	7, C	FAN BASE AS.
CS-A50BD2P	8	P45-T06980	P45-T04270	7, C	FAN BASE AS.
CS-A28BD2P	13	P42-T02980	P42-T03300	7, C	PANEL SIDE R AS.
CS-A34BD2P	13	P42-T03460	P42-T02980	7, C	PANEL SIDE R AS.
CS-A43BD2P	13	P42-T03460	P42-T02980	7, C	PANEL SIDE R AS.
CS-A50BD2P	13	P42-T03460	P42-T02980	7, C	PANEL SIDE R AS.
CS-A28BD2P	14	P42-T02200	P42-T03000	7, C	PANEL SIDE L AS.
CS-A34BD2P	14	P42-T01890	P42-T02200	7, C	PANEL SIDE L AS.
CS-A43BD2P	14	P42-T01890	P42-T02200	7, C	PANEL SIDE L AS.
CS-A50BD2P	14	P42-T01890	P42-T02200	7, C	PANEL SIDE L AS.



© 2003 Matsushita Industrial Corp. Sdn. Bhd.
(11969-T). All rights reserved. Unauthorized copying
and distribution is a violation of law.

Part Number					
Model No.	Ref. No.	Original Part No.	New Part No.	Notes	Part Name & Descriptions
CS-A24BD2P	21	A53D0003A	A73C1168	7, C	PCB ASSEMBLY
CS-A28BD2P	21	A53D0003A	A73C1168	7, C	PCB ASSEMBLY
CS-A34BD2P	21	A53D0003A	A73C1168	7, C	PCB ASSEMBLY
CS-A43BD2P	21	A53D0003A	A73C1168	7, C	PCB ASSEMBLY
CS-A50BD2P	21	A53D0003A	A73C1168	7, C	PCB ASSEMBLY
CS-A24BD2P	-	-	P46-T04000	5, C	WIRE HARNESS ASS'Y IHA
CS-A28BD2P	-	-	P46-T04000	5, C	WIRE HARNESS ASS'Y IHA
CS-A34BD2P	-	-	P46-T04000	5, C	WIRE HARNESS ASS'Y IHA
CS-A43BD2P	-	-	P46-T04000	5, C	WIRE HARNESS ASS'Y IHA
CS-A50BD2P	-	-	P46-T04000	5, C	WIRE HARNESS ASS'Y IHA

File this Parts Change Notice with your copy of the Service Manual.