

## DS-Net “wireless remote controller non-compatibility”

It should be clear that wireless remote controllers cannot be connected to Daikin's DS-net system.

The reason for this non-compatibility is explained as follows;

When using a wireless remote controller, the sub wiring line must be used for connection, however DS-net also requires connection to this line.

If both devices occupy the one line the abnormal condition will occur.

This is explained in more detail on page 51 in the D-BACS Design Guide ED 72-021

